

## Propellers

Status	Subject	Detail	Reference information	TNS
Airworthiness Directives as listed				
<b>HOFFMANN SERIES PROPELLERS</b> ( <u>Luftfahrt-Bundesamt Airworthiness Directives</u> ) (LBA)				
UK Service Station – Skycraft Services Ltd, 01763 852150				
M	HO-V62 R/L 160T	Calibration of tachometer and inspection of propeller blades.		
		Introduction of improved blade root retention	AD83-150/4, SB4C	
M	HO-V 123 (-)/180R	Inspection for cracks in the coating on the suction side near the blade shaft	AD88-20, SB6 EB	
M	HO27 & HO4/27	Strength problems on propeller mounting Bolts	AD1998-322/2, SB61-11-03E10 RA	
M	Overhaul Periods	See TNS		06/91
	Hoffmann VP Propellers	Pitch change rod failure		10/00
M	Hoffmann propellers	revised overhaul periods for some types	SB E1Y	06/02
M	HO-V62R/L 160BT	Pitch change rods (AD applicable to Diamond H36 Aircraft)	AD-D-2005-370 Hoffmann SB 61-11-03E	10/05
		Will be embodied on all other HO-V62 props at next overhaul		
M	HO-V343K	Inspections to detect hub failure	EASA AD 2006-0110	3-2006

### **MT PROPELLERS** (Luftfahrt-Bundesamt Airworthiness Directives) (LBA)

M	MTV-1(-)	Possible loss of propeller blade	AD90-214 iss2, SB TM4A	
M	MTV series	Change of emergency procedures for powered gliders	AD92-367, SB TM6	
M	MTV series	Correction to AD92-367	see AD 92-367	
M	MTV-1(-), -7(-), -10(-), -17(-), -18(-) and -20(-)	Replacement of the electric motor of the propeller servo	AD93-088/2, SB TM7	06/93
M	MTV-3-B, MTV-3-B-C	Hub, crack inspection and rework or replacement of the hub	AD97-006/5, SB12	04/97
M	MTV-9	Propeller blades, inspection of the torque and if		

Page 1

BGA Compendium [11/07](#)

## Propellers

Status	Subject	Detail	Reference information	TNS
M	MTV-3	applicable replacement of the blade root lag screws Propeller blades, inspection of the torque and if applicable replacement of the blade root lag screws	AD1999-081/2 SB17A AD1999-082/2, SB17A	
M	MTV-1,2,3,5,6,7,9,10,11,12,14,15,17,18,20,21,22 & 24 Blade	Inspection to prevent sudden loss of metal erosion sheath	AD 1994-098/2, SB 8A	10/03

### TOP PROPELLERS

M	All models Blades	Propeller blade thickness inspection	AD2001-345, SB 32.110/25/1	12/01
---	-------------------	--------------------------------------	----------------------------	-------

### GENERAL PROPELLER INFORMATION

	Mount bolts	Check bolt torque regularly to prevent damage		12/97
	Blades	Seal minor damage to propeller blades to prevent Moisture absorption and expensive repair.		
I	Repairs	Only approved minor repairs allowed. Return propeller to manufacturer or agent for other repairs		04/03

### TECHNOFLUG PROPELLERS

M	Maintenance	Self Sustainer propellers are subject to the following		
		<a href="#">Annual Check</a>		
		<a href="#">200 hour overhaul</a>		
		<a href="#">Details on the Schempp-Hirth web site</a>		5-2007