

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
--------	---------	--------	-----------------------	-----

Contact: UK Agent: - Zulu Glasstek, Peter Wells Tel 01844 201028 or 208157

Current AD's available on LBA web site. www.lba.de

Airworthiness Directives indicated "I" are for information and can be considered as embodied on pre 9/2003 BGA aircraft. Aircraft imported into the UK after 9/2003 require all AD's to be embodied as applicable.

Schleicher TN's can be viewed at http://www.alexander-schleicher.de/index_e.htm All Technical notes should be reviewed to determine applicability.

Schleicher General

M	Structure	Structural inspection 5 year repeat due	BGA 042/07/2004 issue 3	2-2009
M	Elevator control	Bent elevator control arms now extended to all types with plate alloy elevator arms and inspection requirements clarified	BGA 042/07/2004 issue 2	5-2009

Rhönlerche II ("Ka 4") (Brief descriptions translated from German text. See AD for full details)

I	Controls	Tail plane pins, add. control pulleys, cable guide	AD 12, TN 4b	
M	Landing gear	Suspension and reinforcement to rib and wing spar	AD 12, TN 5	11/77 & 01/78
I	Controls	Inspection after hard landing	AD 8, TN 6	
I	Controls	Upper rudder hinge bracket reinforcement	AD 10, TN 8	
I	Wings	Reinforcement of nose rib 4 and spar cap strip	AD 14, TN 8	
I	Controls	Free movement of the elevator control cable	AD 5/62, TN 9	
I	Controls	Inspection of rear control column	AD 2/63, TN 10	
I	Controls	Aileron mass balance	AD 4/67, TN 12	
M	Controls	Control column reinforcement	AD 75-166, TN 13	02/78 & 10/75
M	Controls	Control cable clevis	AD 77-286, TN 14	02/78 & 11/77
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A		
		introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04

Ka-6 series (except K6E) (Brief descriptions translated from German text. See AD for full details)

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
I	Tail plane	Tail plane locking pins (K6 & Ka6B)	AD 1960-007, TN 2/1	
I	Structure	Inspection for shrinkage cracks (Ka6 & Ka6B)	AD 1960-007, TN 2/2	
I	Wings	Web reinforcement of the outer wing spar	AD 1960-005, TN 3	
I	Controls	Elevator brackets	AD 1962-002	
I	Controls	Additional elevator push rod bracket	AD 1962-004	
I	Controls	Reinforcement of air brake push rod	AD 7/62, TN 7	
M	Controls	Elevator No 1 rib inspection	AD 72-7/3, TN 21	
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Controls	Elevator drive engagement check	BGA 003/07/2000	08/00
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04
M	Flight controls	Elevator trim tab control horn end rib inspection	BGA 045/07/2005 issue 1	

K6 E (All flying tail plane)

I	Wings	Web reinforcement of the outer wing spar	AD 1960-005, TN 3	
I	Controls	Reinforcement of air brake push rod	AD 7/62, TN 7	
I	Systems	Attachment of variometer flasks	AD 68-109, TN 17	
M	Controls	Extension of spar tube in the all flying tail plane	AD 70-86, TN 18	
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006

K6 In Service Reports (Advisory)

Wing ribs 1 & 2	inspect for cracks	03/82 & 10/80
Tail plane front mounting	damaged by carrying handle - delete handle	06/83
Elevator drive rod	damaged near elevator by misrigging	06/83
Tail plane rear mounting	cracked & worn fittings, loose & corroded bolts	06/96, 04/94 & 06/91
Canopy catch	insecure	06/94
Trim spring & lower mounting	bracket corroded/cracked – inspect	06/86
Airbrake paddles delaminated	bolt and glue paddles to aluminium parts	BGA
Tail plane insecure	reinforce/repair mounting as necessary	04/87

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
	Air brakes	Cracks in air brake aperture		02/00

K-7 (Brief descriptions translated from German text. See AD for full details)

I	Wings	Web reinforcement of the outer wing spar	AD 5, TN 2	
I	Controls	Exchange of the middle elevator hinge bracket	AD 15, TN 3	
I	Structure	Steel tube reinforcement	AD 19, TN 4	
I	Controls	Additional elevator push rod bracket	AD 4/62, TN 7 & TN 8	
I	Controls	Inspection of rear control column	AD 2/63, TN 10	
M	Controls	Elevator rib 1 inspection	AD 72-7/3, TN 18	
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Rear stick	comes out of mounting lock into place		04/83
M	Canopy	Strap fouls rear stick/brake lever. Fit secondary strap.		
M	Controls	Elevator drive engagement check	BGA 003/07/2000	08/00
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04
M	Flight controls	Elevator trim tab control horn end rib inspection	BGA 045/07/2005 issue 1	

K7 In Service Reports (Advisory)

Fuselage centre section	cracks in welds		06/85
Rear canopies detach in flight	locating lugs removed or badly worn		02/87 & 08/91
Rudder cable	may catch under rear airbrake pivot nut, fit guard if necessary		12/99
Air brake pivots	Pivot bolts may migrate if not locked		02/00
Jammed open in flight	Control stop jumped past stop tube		02/01

K-8 (Brief descriptions translated from German text. See AD for full details)

I	Wings	Web reinforcement of the outer wing spar	AD 5, TN 1
I	Weight and balance	Trim weights	AD 13, TN 2
I	Controls	Exchange of the middle elevator hinge bracket	AD 17, TN 3
I	Controls	Additional elevator push support	AD 4/62, TN 6 & TN 7
I	Controls	Reinforcement of air brake push rod	AD 2-62/2 & 70-50, TN 8, 9 & 10.
M	Controls	Elevator rib 1 inspection	AD 72-7/3, TN 23

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
M	Canopy	Latch inspection	AD 80-158, TN 21	08/80 & 07/76
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Various	canopy cord, rudder pedals, elevator control, Fuselage tubes		
		Manual amendments, wing pin diameter	AD 96-005, TN 24	04/96
M	Elevator drive	Inspection of engagement	BGA 003/08/2000 Iss. 1	08/00
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A		
		introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04
M	Flight controls	Elevator trim tab control horn end rib inspection	BGA 045/07/2005 issue 1	

K8 and K18 In Service Reports (Advisory)

Wing ribs 1&2	inspect for cracks	10/80
Control system	lower mounting in fuselage centre - cracked - inspect	03/82
Seat back to be fitted (K-8)	to prevent parachute catching between tubes	11/82
Elevator hinge pins	not secure - inspect	12/86
Rudder cables	fouling elevator rod	02/92
Elevator hinge	cracked	06/92
Tail plane mountings	cracked and corroded	04/93
Fuselage tubes	X-ray inspection is possible	04/97
Elevator push rod	check for bending	04/96 & 04/97
Elevator control (K8)	Operating bearing fitted to incorrect holes in operating arms.	1-2007

ASK-13 series (including Jubi GmbH aircraft)

I	Controls	Installation of additional fairlead in the rudder cables	AD 1/68, TN 1	
I	Controls	Installation of additional fairlead in the brake cable	AD 68/53, TN 2	
I	Landing gear	Installation of buffer plates	AD 68/110, TN 3	
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Controls	Elevator rib 1 inspection	AD 72-7/3, TN 12	
M	Wings	Inspection of main fittings	AD 91-144, TN 13	
M	Controls	Inspection of airbrake bearing brackets	AD 91-173, TN 14	
M	Rear stick	comes out of mounting lock into place		04/83
M	Canopy	Strap fouls rear stick/brake lever. Fit secondary strap.		

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
M	Elevator	Inspection for bent elevator arms	BGA 004/08/2000 Iss 1	08/00
R	Controls	inspection of aileron and air brake control support brackets	BGA 008/10/2000 Iss 1	10/00
M	Elevator drive	Inspection of engagement	BGA 010/12/2000 Iss 1	12/00
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A		
		Introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04
M	Flight controls	Elevator trim tab control horn end rib inspection	BGA 045/07/2005 issue 1	

ASK 13 In Service Reports (Advisory)

Canopy opened in flight	improperly locked (lack of lubrication) - colour code open/shut	02/87
Wheel brake	lug failure	10/75
Canopy jettison	inoperative and hinge fractured - lack of lubrication	02/91
Weak link reduced to 850 Kg	max winch/auto speed increased to 60 kts	12/93
Aileron balance weight supports	corroded	02/94
Airbrake drive behind rear seat	torque tube failure near drive lug weld	04/97
Air brake pivots	Pivot bolts may migrate if not locked	02/00
Rudder pedals	Failure of tube at attachment to pedal	04/00
Ballast weights	Unsecured ballast fouling controls due to bolt failure	04/00
Landing Gear	Suspension "Donuts" displaced after heavy landing and restricting controls	08/02
Spin training	In extended weight category, K13's are approved for spin training whilst operating. Other aerobatics prohibited.	1-2007
Air Brake Control	Rear Air Brake lever broken at rod attachment bearing location	6-2008

ASK-14 also see general and airbrake sections

M	Controls	Elevator tube spar inspection	AD 70-86, TN 3	
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Fuel system	Fuel tank	AD 89-121, TN 6	10/89
M	Controls	L'Hotellier connectors	AD 1993-001/3	
R	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A		
		introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006

ASK 16

M	Landing gear	Wheel bolts modification	AD 77-234, TN 8	01/78 & 11/77
---	--------------	--------------------------	-----------------	---------------

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Fuel system	Fuel tank	AD 89-81, TN 10	10/89
M	Controls	L'Hotellier connectors	AD 1993-001/3	
R	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006

ASK 16 In Service Reports (Advisory)

	Control tubes in the wing	corroded		02/92
--	---------------------------	----------	--	-------

ASK 18

M	Controls	Cable inspections Nicropress sleeves	AD 82-216	
M	Controls	Elevator rib 1 inspection	AD 72-7/3, TN 6	
M	Controls	Elevator drive engagement check	BGA 010/12/2000	12/00
M	Structure	Structural inspections Part 1 compliance by 01/10/04, Part 2 & 3 by next C of A introduction of 5 year repeat inspection	BGA 042/07/2004 issue 3	1-2006
M	Flight controls	Elevator rib 1 inspection increased frequency to every year	BGA 043/07/2004 issue 1	08/04
M	Rudder control	Inspection & modification of rudder cable guide tube	BGA 026/03/2002 Issue 1	
M	Flight controls	Elevator trim tab control horn end rib inspection	BGA 045/07/2005 issue 1	

K8 and K18 In Service Reports (Advisory)

	Wing ribs 1&2	inspect for cracks		10/80
	Control system	lower mounting in fuselage centre - cracked - inspect		03/82
	Seat back to be fitted (K-8)	to prevent parachute catching between tubes		11/82
	Elevator hinge pins	not secure - inspect		12/86
	Rudder cables	fouling elevator rod		02/92
	Elevator hinge	cracked		06/92
	Tail plane mountings	cracked and corroded		04/93
	Fuselage tubes	X-ray inspection is possible		04/97
	Elevator push rod	check for bending		04/96 & 04/97
	Elevator control (K8)	Operating bearing fitted to incorrect holes in operating arms.		1-2007

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
	<u>Schleicher Wood / Metal general - In Service Reports (Advisory)</u>			
	Flying controls	Aileron horn and balance weight support are corroded		04/05
	Wheel brake cables	to be wire wiped at turnbuckle to prevent air brake restriction		10/66
	Wings, damage	by water/damp ply separation & spar damage	02/00, 10/83, 08/83 & 08/76	
	Rudder pedals (front)	cracked and bent - clips broken	08/94 , 06/84 & 02/77	
	Rudder hinges (top & bottom)	cracked	04/87, 02/84, 04/80 & 01/79	
	Rudder mounting brackets	cracked	04/91 & 02/90	
	Lower rudder hinge mount	cracked repair and reinforce with 2 ^{mm} ply as necessary		06/97
	Elevator drive (not Ka-6E & 14)	check full engagement after repair		06/87
	Rigging of ailerons	both neutral with elevator neutral		08/87
	Fin attachments (rear)	damage by water and corroded	08/98, 06/95, 01/93 & 02/90	
	Steel tubes around wheel boxes	rusted through - lack of drainage		04/90
	Trim tab root rib	glued joint failure tab detached - introduce drain holes		08/90
	Rear fuselages (ASK 13 & K 7)	structural failures		02/91
	Control connectors at wing root	bending of thread - adjust correctly/fit airbrake system stop half connector top may be cut away to give clearance with bellcrank		02/91
	Trim system turnbuckles	failure at trim lever		08/91
	Fin attachments	ply cracked (front) & rotten at bottom	08/87 & 06/92	
	Canopy locks worn Ka 2/2b (& Ka 7?)	canopies open during sideslips		08/97
	Tail plane mounting bolt	threads wear - replace bolts as necessary		06/99
	Rudder Pedal Failure Ka13	Reported failure.		04/00
	Unsecured ballast weight	Attachment bolt failed		04/00
	Bogus parts	Problems with bogus parts		04/00
	Fuselage fittings	K7 low wing conversion found with excessive material removed from wing attachment lugs		4/2006
	Control connections	K13 (applicable to other types) Aileron disconnect safety/locking pin bent and missed rigging pin hole Replace safety pins if bent or distorted		4/2006
	Elevator control (K8)	Operating bearing fitted to incorrect holes in operating arms. Could also affect other similar types		1-2007
	Structure	Delaminated stern post after hard ground strike		2-2007
	Rudder pedals	Saddle clamps broken causing pedals to jam on fuselage frame		2-2007
	Wheels	Broken tie bolts. Take care when removing wheels, deflate if necessary		2-2007
	Airbrake stops insecure	rivet them into place		07/76
	Cross-link in centre section	(not ASK-13) cracked and twisted - reinforce	04/89, 12/88 & 12/84	
	Airbrake handle failures	cracks at rivet and bearing holes	10/95, 04/94, 06/92 & 10/88	
	Airbrake paddles (lower)	delamination, lack of drain holes	04/93 & 04/89	

Schleicher (Germany) Wooden / Metal Structure Aircraft

Status	Subject	Detail	Reference information	TNS
	Airbrakes (Ka-2B & K-7)	reduction of travel and loads		02/85 & 08/89
	recommended airbrake travel	K-7, restriction to prevent heavy landings	Paddles should not quite clear cut-outs in wings.	08/99
	Jammed open in flight	Operating arm attach. Bolt to paddle fouling wing box. Incorrectly positioned slot		02/01
	ASK 13 Airbrakes	Continuing problems with cracked "A" brackets at wing root – see pervious		08/03
	Controls (K6cr and poss others)	Aileron disconnect due QR safety clip fouling ctr. Section shelf. Ensure only correct size clip is used		10/03
	Controls (K13 and others)	damage to control rods in ctr. Section due to rigging damage. Check for bent rods and fittings.		10/03
	Fin attachment	It is recommended to pack lower face of fin against fuselage tubes to prevent flexing		04/04