



## British Gliding Association Aircraft Inspection

Mandatory

|                        |             |
|------------------------|-------------|
| Number:<br>010/12/2000 | Issue:<br>1 |
|------------------------|-------------|

Date: 11<sup>th</sup> December 2000

Subject: ASK 13 and ASK 18 Elevator Engagement

Applicability: Schleicher ASK 13 and ASK 18

Accomplishment: At next and subsequent C of A inspections and during inspections of rear fuselage.

Reason: Incorrect positioning of elevator linkage pivots or damage during rigging or following accident damage causing misalignment of elevator control arm ball bearing in drive rod and possible disconnection in extreme conditions.

Instructions: It may be necessary to remove one half of the elevator to accomplish this inspection.  
Inspect the engagement of the elevator control arm ball bearing into the elevator control rod drive "U".  
The engagement of the bearing must be at or slightly below the centreline of the "U" during all positions of elevator travel.  
To correct an out of tolerance condition replace any worn or incorrect parts with genuine Schleicher items if condition still exists replace or modify link upper aft bracket. The K8 "Automatic Elevator Connection" drawing may be used as a guide.

Approved By  
Jim Hammerton, Chief Technical Officer


Issued by - The British Gliding Association Ltd, Kimberley House, Vaughan Way, Leicester, LE1 4SE, U.K.

Note: Mandatory inspections must be recorded in the aircraft log book, unless specified, and certified by an appropriately rated BGA inspector.  
Optional inspections should be entered into the D.I. book or log book as appropriate. Optional inspections may be certified by a BGA Pilot instructor.

Possible sources of mistakes in the automatically elevator connection  
of the types Schleicher Ka 2 and Ka 2B, Ka 6, K 7 and K 8. ( US 7G1, 7G3, 7G4 )  
This point should be given special attent at the inspections.

1. Correct make:

Must be in center.  
or ballbearing  
some what lower



$$a_1 = a_2$$

$$b_1 = b_2$$

b2 may be wider until  
4 mm, in no case  
smaller. Check it with  
a pair of compasses.  
Therefore disassemble  
one half of elevator.


2. Ball bearing too high.



A new bearing support  
"B" is to be made with  
adjusted measures if  
the above dimensions  
are not correct.

3. Parallelogram gearing not correct:

too narrow



goes out at deflection  
"push".

The inverse case can be, but is not so serious.

4. The stop of the elevator control must be at the seat. When the control  
is stopped at the rear, the push rod may be cracked by the very high  
hand power.

\*Instructions on this drawing also applicable to  
ASK 13 and ASK 18 Aircraft\*

THE  
B.G.A.  
LTD.

THE  
B.G.A.  
LTD.

4.7.62. Kari