

British Gliding Association Aircraft Inspection

Recommended

Number:	Issue:
028/04/2002	1

Date: 29th April 2002

Subject: Landing Gear – Crack inspection

Applicability: Stemme S10 series

Accomplishment: As soon as possible and after heavy landing or operation on rough ground unless reinforced wheel radius arms have

been fitted

Reason: Failures have been reported of the main landing gear wheel carrier radius arms at the hinge end.

Instructions: Inspect both main landing gear wheel carrier radius arms at the welded joint where the round tube is attached to

the U shaped hinge fitting.

Inspect for any signs of cracking along the weld edge. Discoloration, rust marks or spots are cause for further

investigation. The cracks can be hidden under the paint in the early stages of development.

If any cracks are found, the radius arms must be replaced before further flight.

It is believed that Stemme are developing a reinforced radius arm and will raise a Service Bulletin in due course.

Approved By Jim Hammerton, Chief Technical Officer