## **BGA accident/incident summaries**

adjacen	<b>Type</b> PW5 op during winch la t field, losing the v	vingtip skid and da	<b>Date, time</b> 10/08/17, – leased, but the wingtip caught the ground a imaging the gelcoat. As it was a first flight o t. The reported wind speed was calm.			
140 Wheel-u	Discus Ip landing after a l	minor ocal soaring flight,	10/08/17, 16:00 resulting in scoring to the underside of the	none fuselage.	not reported	
141Grob 102substantial11/08/17, 12:30minor467Landed in gorse short of runway. After the wave lift died off, the pilot recognised that the glide to the hilltop airfield was marginal, but he elected to test the ridge lift before either landing at a nearby airfield or returning to the club. There was just enough reduced sink to entice the pilot to continue to the club, but not enough lift to climb to a safe circuit height. Rejecting a downwind landing, the pilot continued along the ridge before turning onto a very low base leg for the into wind runway. Losing height behind the ridge, the pilot was careful to maintain a safe speed, but felt the glider hit some trees while turning onto final approach. A wingtip caught on a bush while rounding out short of the runway, yawing the glider which then touched down sideways. The pilot suffered some severe bruising and went to hospital for a check up. The glider fuselage was severely damaged around the cockpit.						
			13/08/17, 18:10 Indercarriage lever disengage while turning I into place, subsequently landing with the w		not reported lown to see the lever	
	the rear of the fus		15/08/17, 17:00 inal glide, approx 10km from the airfield. Aft of the fin. A previous owner had groundloop			
	ng side slips, the ca		16/08/17, 13:30 py had been confirmed as locked shut durin during a stall turn. The perspex damaged th			
	HpH Shark tery caught fire du vestigation.	substantial Iring landing. A CC	10/08/17, 13:20 02 extinguisher had little effect, the fire was	none put out using a foa	not reported am extinguisher.	
149JS1substantial19/08/17, 17:10minor3,000Competition field landing crash following failed engine start. After rounding the final control point, the pilot was heading back to the airfield, uphill into a strong wind. He tried to start the engine at about 3km and 320ft aal. When that failed to start he flew a hurried circuit into the field below, but did not have time to dump the water ballast or lower the undercarriage. The glider landed heavily and caught a wingtip, groundlooping and damaging the fuselage, wing and tailplane.						
30° off t	he runway direction		19/08/17, 15:25 . The low airtime pilot appeared not to suffic ed downwind of the runway on approach be ame tubes.			
151LS4destroyed20/08/17, 13:15none50Overshot field landing. The 440m long field might have been adequate, but the light wind, slight downslope and wires at the upwind end were not in the pilot's favour. The circuit was flown too close to the small field and, despite flying a 360° turn on final approach, the glider crossed the threshold still 200ft agl. After floating down the length of the field, the glider hit the top of the boundary hedge before falling onto an access road on the other side. The port wing broke off in the impact.						
circuit w	vas cramped and c	lid not adequately	20/08/17, 15:20 ht on type, the pilot selected a field and sta allow for the crosswind, resulting in the pilo after landing in crop, breaking the fuselage.	t flying over the cl		
153	Astir	minor	20/08/17, 12:00	none	342	

Heavy landing broke undercarriage door.

# **BGA accident/incident summaries** *continued*

AIRCRAFT PILOT							
<b>Ref</b> 154	<b>Type</b> Puchacz	Damage substantial	Date, time 25/08/17, 11:40	<b>Injury</b> serious	P1 hours 89		
Airbrakes came open during aerotow take-off. The tug pilot tried to radio the glider pilot, but the glider pilot had not turned on the avionics before take-off. The tug pilot, concerned about clearing a line of trees, released the rope. The glider hit the top of the trees before landing heavily, fracturing the pilot's lower back. A cockpit camera suggests that the pre-flight checks were not performed fully.							
155 Heavy la	T-61 anding. The report	substantial suggests that the p	29/08/17, 16:30 oilot may have rounded out a little high and	minor/none lost energy before	4 e touching down.		
			20/08/17, 16:00 A bow developed during the tow, the instru ruck the canopy before hitting the tailplane		518 released before the		
162K-21substantial31/08/17, 13:20none/none3,440Heavy landing and groundloop in field. Returning after a cross-country training flight, the glider flew into heavy rain a few miles short of the airfield. The P1 set up an approach into a known field near the club. On final approach, the P2 warned of cables in the field. The instructor was aware of the cables and knew them to be parallel to the landing direction but, with visibility restricted by the wet canopy, elected to turn away to be safe. While turning at low level, with wet wings in poor visibility, the instructor was unable to round out properly and the glider struck the ground nose first before groundlooping. The nose wheel was forced up into the fuselage and the tailplane detached during the groundloop.							
stick too	o far forward and a	Ithough the instruc	31/08/17, 11:30 o the instructor prompted the student to lov ctor took control he was unable to prevent t , the glider had fuselage and wing damage.				
168Supercubsubstantial24/09/17, 13:40none378Prop strike. At the end of the take up slack, the tug pulled the glider forward slightly, leaving some slack in the rope. When the all out signal was given, the tug accelerated until the rope became tight again; the tug slowed while the glider lurched forward, the tug then tipped onto its nose, damaging the propeller.							
Incident	s						
143 The pilo	Ventus t accidentally drov		13/08/17, 9:15 wingtip, destroying the winglet and damag	- ing the outboard p	3,000+ Part of the wing.		
147	PA 18	none	13/08/17, 10:50	-	-		
Tug exhibited poor acceleration and directional control. After helping to launch a competition grid, it was discovered that the port wheel parking brake was engaged.							
148	Duo Discus	none	13/08/17, -	-	-		
The tailplane was found to be not secured while performing positive control checks. Although the rigging tool had been removed, the securing pin was not through the tailplane lug, the tailplane was sitting proud of the fin and the front of the pin protruded through the front of the fin. The glider had been rigged and flown the previous day.							
156	K-21 K-21	minor minor	17/08/17, 19:30	-	-		
One glider was towed to the back of the launch queue. The pilots were preparing to disconnect the tow rope when the club mule tow vehicle lurched forward, pulling the attached K-21. A wingtip struck the mule, the other tip struck the parked K-21 rudder.							
158K-13none27/08/17, pmTug upset at about 350ft ato. The glider P1 moved the stick forward after losing sight of the tug, but could still not see the tug. He reached for the release, but it seemed not to work; looking down he saw the airbrakes were open and then pulled the release before closing the airbrakes. Both aircraft landed safely on the airfield. The pilot had been flying his own glider for two hours, only being asked to fly this trial flight as there was a shortage of instructors.							
159	Astir	none	27/08/17, -	none	6		
Wheel-u	ıp landing.				Continued on p68		

### **BGA accident/incident summaries** continued

AIRCR	AFT			PILOT	
Ref	Туре	Damage	Date, time	Injury	P1 hours
160	DG-500	none	27/08/17, 14:40	none/none	350
Whee	I-up landing. The F	2 felt ill a few n	ninutes into the flight; the P1 made	e an expeditious return to the a	airfield, but forgot to lower
the ur	ndercarriage.				
161	Discus	none	27/08/17, 15:30	none	74
The ca	anopy was not pro	perly locked be	fore take-off, despite the pilot's p	re-flight checks.	
164	Supermunk	minor	06/07/17, 17:15	none	-
Engin	e cylinder cracked	during tow. Tug	g and glider returned safely to the	e airfield.	
165	DG-505	none	16/09/17, 13:30	-	1296
The P	1 demonstrated ho	w to correct for	r crosswind drift during a winch la	aunch. The P2 continued the co	prrection and by the time
the gl	ider reached the to	op of the launch	it was upwind of the airfield. The	e weak link broke and the strop	and hardware fell into the
club c	ar park, fortunatel	y without injury	or damage.		
166	K-21	none	06/08/17, 14:00	none/none	700
Glider	landed off the air	field after simul	ated winch launch failure. The inst	tructor pulled the release at 40	Oft agl as part of a pre-
briefe	d exercise, the P2	recovered and e	elected to land ahead. Realising th	nat they were running out of ai	rfield, the P1 took control
and m	ade a safe landing	in a crop field	adjacent to the airfield. The wind	had been light and variable, th	e club changed runway
after t	he incident.				
167	ASW 20	none	15/08/17, 11:00	none	-
Heavy	landing. The glide	er dropped a wi	ng at the start of the winch launc	h the wingtip scraping the gro	und for a few seconds. The

Heavy landing. The glider dropped a wing at the start of the winch launch, the wingtip scraping the ground for a few seconds. The launch signaller gave the stop signal but the pilot raised the wing and continued the launch. There was enough momentum in the cable to accelerate the glider to flying speed, but the glider then ran out of energy at about 6ft agl before landing heavily. The BGA *Safe Winch Launching* booklet advises launchpoint controllers to give the stop signal immediately if a wing goes down; the CFI's report suggests that signallers should continue to give the all out signal even if the wingtip touches the ground.

During BGA Club Safety Officer seminars it was proposed that, to further encourage reporting, it would be a good idea to remove site names from summaries. This has been reflected in the summaries on these pages. Edward Lockhart continues to provide a little extra detail, where available, in these listings. We would also like to publish (anonymously) your stories of particular flights that have taught you a valuable flying lesson. Please send details to *editor@sailplaneandgliding.co.uk* or by post to the address on p3.



### Don't fly your glider over the winter? Then why pay for full flight risk cover? Contact Forbes for a reduced premium including winter ground risk only cover

#### At Forbes our friendly team offers:-

- Highly competitive pricing for individuals and clubs.
- Sound advice you can trust.
- A proven smooth claims handling service.
- Z Exclusive policy wording only available to Forbes.
- 46 years of gliding/100 years of insurance experience.
  1 he experience of a former Glub CFL current BGA.
- Full Cat and CAA SLMG Instructors
- Competition/Mountain/Overseas Experience
- Z Many years of service on Club Committees
- All aspects of aviation and business insurance.
- / 24/7 Mobile Phone Availability

If your broker answers no to any of the above points then please talk to Forbes