

## Pilatus (Switzerland)

Status	Subject	Detail	Reference information	TNS
<b>Contact:</b> Dietmar Poll, EWMS Technomanagement Ltd, Newmatt 18, CH-1736 St Silvester, Switzerland.				
<b><u>PILATUS B4</u></b>				
M	Canopy catch	fit limiting cable	SB 1001	
M	Crotch strap	fouls rudder cables	SB 1002	
M	Aileron	bell crank pin fouling	SB 1003	
	Control systems	lubrication	SL 101	
M	Seat latch pins fouling	serial numbers 1→140	SL 102	
M	Gear down lock cracks	fit thicker locking plate		07/76
	Rudder cables	escape from keyholes guides - wire or tape around guides		12/76
	Elevator drive rods	rivets loose in fittings		12/85
M	Airbrake system	fit stops & check rivets for looseness	AD 86-041, SB 1004	04/86
M	Drag spar pin improperly engaged	inspect & modify if necessary		08/88
M	Drag spar bushes	to be secured may fall out of de-rigged gliders		10/75 & 10/90
	Fin to fuselage joint corrosion	inspect for paint cracks		04/96
R	Tailplane	Tailplane mounting inspection following H/Landing, Ground loop Or severe turbulence	BGA 018/05/2001 issue 2	06/01
M	Flying controls	Inspection of CC support (B4-PC11, 11A, 11AF)	AD 2004-491, SB 1005	04/03

### **Pilatus B4 In Service Reports (Advisory)**

	<a href="#">I</a>	<a href="#">Landing gear</a>	<a href="#">Operating arm tubular rivet failed</a>	<a href="#">1/2009</a>
--	-------------------	------------------------------	--	------------------------