

Stemme (Germany)

Status	Subject	Detail	Reference information	TNS
Contact: UK Agent Mike Jefferies 01277 823066				
LBA & EASA Airworthiness Directives				
<u>STEMME S10, V & VT</u>				
M	Rudder cable turn buckle	replace	AD 94-260, SB A31-10-018	10/94 & 02/95
M	Pitot tube 'O' ring	replace	AD 92-197, SB A31-10-003	06/95
M	Fuel Filter	Inspection of fuel filters and amendments to flight manual	AD 95-273, SB A31-10-021	10/95
M	Tailplane rear fitting	inspect for cracks	AD 96-300, SB A31-10-022	12/96
M	Propeller blade fork	exchange, inspect & modify	AD 95-177/2, SB A31-10-020	06/95 & 04/97
M	Flap drive rocker replacement	before 31/3/99	AD 1998-324, SB A31-10-017	08/98
M	Elevator drive system cracks	inspections before next flight & parts replacement by 31/3/99	AD 1998-323-3, SB31-10-032	08/98 & 12/98
M	Wastage control & Oil tubes	fit redesigned parts	AD 1998-400, SB31-10-034	12/98
M	Air brakes & landing gear	Inspections and modifications	AD 2000-,369 SB A 31-10-055	12/00
M	Propeller	Pitch change fork and gearbox modifications	AD 1999-224/5, SB A 31-10-051	04/01
M	MAN Drive shaft	Inspection	AD 2002-113, SB A31-10-058	04/02
M	Fire protection	Inspection and modification	AD 2002-156, SB A31-10-061	06/02
M	Gear box (action before flight)	Possible failure of 11AG type gearbox	AD2002-389/2, SB A31-10-065	12/02
M	Controls	L'Hotellier ball & socket with lock plates	AD 1993-001/3	
M	Controls	L'Hotellier ball & socket with locking cams	AD 1994-001/2	
M	Flying controls	Aileron control system loose bearings insp/mod	AD-D-2004-443, SB A31-10-069	10/04
M	Fuel hoses (10-VT)	Before flight inspection of fuel hoses	AD D-2005-228, SB A31-10-073	06/05
M	Exhaust	Inspect for cracks	AD 2006-0217, SB A31-10-075	4-2006
M	Fuel system	Inspection of fuel couplings	AD 2006-0310, SB A31-10-077	5-2006
M	Engine Coolant	Coolant replacement	AD 2006-0311, SB A31-10-076	5-2006
M	Propeller	Blade follower replacement	AD 2006-0373-R1-E Correction, SB A31-10-078	1-2007
M	Fuel	Diff fuel pressure sensor	AD 2007-0191-E, SB A31-10-081	4-2007

Stemme (Germany)

Status	Subject	Detail	Reference information	TNS
M	Fuel	Inspection of fuel system connectors (-VT)	AD 2007-0315-E, SB A31-10-082	6-2007
M	Fuel (VT)	Fuel connectors and single ear clamps inspection	AD 2008-0053-E, SB A31-10-083	2-2008
M	Fuel	Pressed fuel lines inspection replacement	AD 2008-0186-E, SB A31-10-084	5-2008

Stemme In Service reports (Advisory)

	Fuel	AVGAS 100LL only		08/95
	Rudder cable wear	at "S" guides on the rudder pedals		10/98
R	Landing gear	Radius arm crack inspection	BGA 028/04/2002 issue1	04/02