Grob (Germany)

Statu	s Subject	Detail	Reference information	TNS				
<u>Contact:</u>								
Product support from Grob http://www.grob-aircraft.com/								
UK Agent Soaring Oxford 01636 525318 (Technical, Tim Dews, Airborne Composites 01985 840981 http://www.airbornecomposites.co.uk/)								
LBA Airworthiness Directives https://www.lba.de/EN/DivisionT/Airworthiness/ADs/ADs.html								
EASA AD list <u>http://ad.easa.europa.eu/</u>								
TYC holder AD and TN and Sb list http://www.grob-aircraft.com/index.php/62.html								
For complex repairs on the 277 form always quote and adhere to http://www.grob-aircraft.com/tl files/pdf/G109/RI-01 2 Standard Repairs.pdf								
<u>Grob G-109 & G-109B</u>								
R	Flying controls	inspection of air brake control rod	BGA 022/10/2001 iss1	10/01				
	G109 In Service Reports (Advisory)							
	Corrosion of bolts	in wing root attachments		06/91				
	Hot air shutter valves	cracked, failed & and butterfly screws loose		10/86, 12/92 & 10/91				
	Rudder Pulleys in wheel brake system	bell crank cracked & failed cracked replace nylon with aluminium		08/92 04/94				
	Tail wheel springs	damage rudder push-rod		06/97				
	Pitch change bolt failure	various causes detailed in TNS		02/98				
	Canopy jettison control	jammed by screws that attach roof trim		06/98				
Ι	Engine oil sump (G109 B) Canopy	Oil sump plug & oil cooler unions loose, check & wire DV Window hinge bolt too short	; lock	06/03 3-2010				
Page 1 BGA	Compendium 05/14							

BGA Compendium 05/14

Grob (Germany)

Status	Subject	Detail	Reference information	TNS
	Elevator Control	Trim control rod fouling tail wheel steering		1-2011
	Rudder pedal (G109) Rudder pedals cracked at adjustment tube attachment			2-2012
	Fuel system filters Various filters in furl system to be checked, fuel flow check at annual		t annual	3-2012
	Elevator rod inspectionRestricted operation of elevator rod with LPS3 ref MSB 817-64-2G2500 engineLoose turbulators in intake manifolds		54-2	3-2012
				3-2012
	G2500 engine	Engine failure due to rocker arm contacting roto cap		4-2012