

## Binder (Germany)

Status	Subject	Detail	Reference information	TNS
--------	---------	--------	-----------------------	-----

**Contact:** Binder Flugmotorenbau GmbH, Alter Frickenhäuser Weg 15, 97645 Ostheim v. d. Rhön +49(0) 97 77 92 00

EASA Airworthiness Directives

**Note: Schleicher ASH 25 TN's Applicable to ASH 25 EB 28.**

### ASH 25 EB 28

M	Flying controls	L'Hotellier couplings	AD 1993-001/3	
M	Limitations	Flight envelope limitation Vne	AD 2006-0218-E	5-2006
M	Flying controls	Elevator pushrod inspection/modification	AD 2006-0346-E	6-2006
M	<a href="#">Flying controls</a>	<a href="#">Aileron hinge bonding joint</a>	<a href="#">AD 2009-0131</a>	<a href="#">3-2009</a>