

## Valentin (Austria) (Germany)

| Status                   | Subject                            | Detail  | Reference information        | TNS           |
|--------------------------|------------------------------------|---|------------------------------|---------------|
| <b>Contact:</b>          |                                    |   |                              |               |
|                          | Taifun                             | KORFF + Co. KG, Unternehmensbereich Luftfahrt, Dieselstrasse 6, D-63128 Dietzenbach, Germany +49 6074 4006 33 |                              |               |
|                          | Mistral C                          | Eichelsdorfer GmbH, Hafenstr, 6, D-96052 Bamberg, Germany +49 951 61413                                       |                              |               |
| <b><u>Mistral C</u></b>  |                                    |   |                              |               |
| M                        | Flight controls                    | Ailerons – residual momentum of ailerons  | AD 2001-089, TN329-013       | 02/01         |
| M                        | Flight controls                    | Vertical air brake steering tube cracks   | AD 2006-058, TN 329-014      | 2-2006        |
| <b><u>Taifun 17E</u></b> |                                    |   |                              |               |
| M                        | Flight controls                    | elevator connection   | AD 85-29, TN 3-818           | 06/86         |
| M                        | Landing gear                       | actuating struts  | AD 85-29, TN 3-818           | 06/86         |
| M                        | Electrical power                   | push button starter   | AD 85-29, TN 3-818           | 06/86         |
| M                        | Fuel valve                         | emergency shut-off  | AD 85-29, TN 3-818           | 06/86         |
| M                        | Stall characteristics              | improvement   | AD 85-129, TN 4-818          | 06/86         |
| M                        | Stall warning device               | introduction  | AD 85-263, TN 8-818          | 06/86         |
| M                        | Tailplane front mounting           | inspect/modify  | AD 86-137, TN 10-818         | CAA           |
|                          | Rudder pedals                      | inspection  |                              | CAA           |
|                          | Airbrake & wheel brake torque tube | weld inspection   | TN 11-818                    | 02/88         |
| M                        | Revision of flight manual          | limitations & inspections   | AD 87-84, TN 11-818          | CAA           |
| M                        | Revision of empty weight & C of G  |   | AD 87-135, TN 12-818         | 10/87         |
| M                        | Airbrake system torsion tube       | deformation- inspect  | AD 91-134, SB 24-818         | 10/91         |
| M                        | Flap lever - cracks in weld        | replace with modified lever   | AD 94-114, SB 28-818         | 06/94         |
| M                        | Wings                              | Safety inspection of main wing attachment   | AD2000-392/2, SB 05/818 iss2 | 10/00 & 02/01 |
| M                        | Wings                              | Wing locking mech. Inspection and check   | AD 2003-051, SB03/818        | 02/03         |
| M                        | Controls                           | L'Hotellier ball & socket with lock plates  | AD 1993-001/3                |               |
| M                        | Controls                           | L'Hotellier ball & socket with locking cams   | AD 1994-001/2                |               |