

ZS Jezow PW (Poland)

Status	Subject	Detail	Reference information	TNS
<u>Contact:</u> THE GLIDER FACTORY "JEŻÓW" 58 - 521 Jeżów Sudecki, ul. Długa 93, TEL/FAX: +48 75 713 21 59				
UK agents – Roger Hurley, CP West Ltd 01432 851886				
<u>PW-5 Smyk</u>				
M	Tow release	Operation	SB 1/PW-5/95	
R	Controls	Airbrake sealing	SB 2/PW-5/95	
M	Documents	Revisions	SB 3/PW-5/96	
M	Flight manual	New issue	SB 4/PW-5/97	
R	Instruments	Modify position of static ports	SB 5/PW-5/97	
M	Canopy frame	check shape	SB 6/PW-5/97	10/97
M	Canopy frame	Errors corrected in previous SB	SB 6/PW-5/97/1	02/98
R	Canopy jettison system	install Roeger hook	SB 7/PW-5/97	10/97
M	Canopy lock handles	replacement	SB 8/PW-5/97	02/98
I	Maintenance manual	revisions	SB 9/PW-5/97	04/98
I	Manuals	Revised re T/E probe in fin	SB BS 17-99-10	
I	Ballast	Optional ballast installation in fin	BI-17-00-12	06/01
R	Total pressure	Installation of optional total pressure and K-1 probe	BS-17-00-13	08/00
M	Structure	Inspection of tail plane attachment joint	AD SP-0028-2001-A, SB BO 17-01-14	
M	Structure	Inspection of cracked joint aft	AD SP-0129-2001-A, SB BO 17-10-15	
M	Bonded joints	Inspection of adhesive bonded joints	AD SP0003-2002A, BO-17-02-16	02/02
M	Air brakes	Inspection of push rod ends	AD SP0086-2003A, BO-17-03-18	02/04
R	Limitations	Increase of altitude ceiling if oxygen is installed	SB BS-17-08-19/ZSJ	4-2008
O	Oxygen installation	Modification	SB BT-17-08-20/ZSJ	4-2008

PW-5 In Service Reports (Advisory)

Seats	Seat back peg jumped out of location during winch launch		02/01
1000 Hr inspection	Reminder to report findings	TSP1/079/2000	08/00

PW-6U

Page 1

BGA Compendium [07/10](#)

ZS Jezow PW (Poland)

Status	Subject	Detail	Reference information	TNS
I	Maintenance manual	Revisions	SB BS-78-01-01	
I	Flight manual	Revision to canopy jettison procedure	SB BS-78-02-02	
O	Elevator	Installation of automatic elevator connector	SB BS-78-02-04	
O	Canopy	Installation opf SWOL breakaway device	SB BT-78-02-05	
M	Flight controls	Inspection of pus rod ends	AD SP-0085-2003-A, SB BO-78-03-06	
O	Canopy	Installation of Roeger hook	SB BS-78-04-07	
M	Canopy	Detailed maintenance instructions	SB BO-78-04-08	
I	Service life	Extension of life	SB BS-78-04-09	
M	Tail plane	Inspection of mounting fitting	AD 2010-0108-E, SB BO-78-10-10	3-2010