

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this  
Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 85-2(A)  
In case of any difficulty, reference should be made to the French original issue.

## CENTRAIR GLIDERS 101 - 101A - 101P - 101AP TYPES

### Handle of towing cable release

Serial numbers : 101 XX 001 to 101 XX 162 included.

In order to prevent an ill timed jettison gear, as soon as possible and in any case before the 1st of March 1985, please check that the mounting and setting of the remote control cable of the hook don't show up a strain or an abnormal disposition according to the CENTRAIR Service Bulletin n° 101-5.

Please enter the compliance of the inspection in the aircraft logbook.

\_\_\_\_\_  
Ref. CENTRAIR Service Bulletin 101-5 and further changes.

\_\_\_\_\_  
**EFFECTIVE DATE : JANUARY 23, 1985**

cZ

Date : 16.01.85

**CENTRAIR GLIDERS 101-101A-101P  
101AP TYPES**

**Ref. 85-2(A)**