

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 85-1(A)
In case of any difficulty, reference should
be made to the French original issue.

CENTRAIR GLIDERS ASW20F, ASW20FL TYPES

ALL SERIAL NUMBERS

Handle of towing cable release

In order to prevent an ill timed jettison gear, as soon as possible and in any case before the 1st of March 1985, please check that the mounting and setting of the remote control cable of the hook don't show up a strain or an abnormal disposition according to the CENTRAIR Service Bulletin ASW20F Nr. 8

Please enter the compliance of the inspection in the aircraft logbook.

Ref. CENTRAIR Service Bulletin ASW20F Nr. 8 and further changes

EFFECTIVE DATE : JANUARY 23, 1985

Date : 16.01.85

CENTRAIR GLIDERS ASW20F,ASW20FL

Ref.: 85-1(A)