

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 86-132 (A)R1
In case of any difficulty, reference should
be made to the French original issue.

Gliders CENTRAIR ASW 20

Flight controls supports

This A.D concern gliders ASW 20.

To assure a proper operation in service prior to further flight accomplish the following :

- check and test the tightening of attachment bolts fixing lateral and pitch supports of the stick on the fuselage frames.

If play is observed, retorque bolts carefully.

Include the Instructions of this A.D in the maintenance inspection program.

Cf.: Service Bulletin CENTRAIR n° 10

This A.D. cancels and replaces original A.D. n° 86-132(A)

EFFECTIVE DATE : SEPTEMBER 3rd, 1986

Dated : 01/10/86

CENTRAIR W 20 Gliders
All serial numbers

Réf. : 86-132 (A)R1