

SLINGSBY AIRCRAFT COMPANY LTD., KIRKBYMOORSIDE, YORKSHIRE.

TECHNICAL INSTRUCTION NO. 38.

Slingsby T.53.B. - Mod. No. 10

INTRODUCTION OF STRONGER LIFTING HANDLE

Lifting Handle item No. 53B-30-167. Iss. 1. is to be replaced by 53B-30-167. Iss. 3.

This modification is Optional.

The parts required for the embodiment of the modification will be supplied by Slingsby Aircraft Co., Ltd., Kirkbymoorside, Yorkshire, England.

SLINGSBY AIRCRAFT COMPANY LTD., KIRKBYMOORSIDE, YORKSHIRE.

SLINGSBY T.53.B. GLIDER

MODIFICATION No. 10

Modification Kit

1. Part No. 53B-30-167. issue 3. Lifting Handle.
2. 2 off AGS/784/11. Split Pins.